

주식회사 씨앤씨

<http://www.data114.com> 데이터복구 및 LCD 수리 전문기업

서울시 영등포구 영신로 220 K N K 디지털타워 701호
영등포 ☎ 02-2655-9990, 강남 ☎ 02-3465-0288, 청주 ☎ 043-236-5114, 부산 ☎ 051-865-1288

Document No : C&C2021-0813-01

ATTN : 리얼컴

Addresser : Data Recovery of CNC. Co,

TITLE : Sheet data recovery success

Maker	P/N	S/N
WD	WDBC3C0020BSL	WXG1E89AVCHF

◎ Symptom and follow-up measure.

1. Symptom

1-1. Impossibility of detection of hard disk.

1-2. Execution of Diagnosis of Hard Disk(PCB and Disk Test)

1) Disk Test → Disk Failure(many number of bad sector, MFT damage)

2) Head Fault → Head access time too late

3) PCB Test → Good

2. TEST Result

1. Harddisk DATA Transfer : Failed

2. Disk Signal Check : Failed

3. Lost cluster rebuild : Failed

◎ It is confirmed of disk failure after test of above. Failure of disk is very difficult to recover data and usually it is impossible to recovery. Therefore, We CNC continue research and investigation for recovery. Hereafter we do our best effort to recover your data.

주식회사 씨앤씨 대표이사

